Facility Estimated Expenses Form

District or Board Name: Greenburgh Central School District

Facility Name: <u>Transportation Garage</u>	티		E	air			
SED Number: 66-04-07-06-5-003	Ictio	ons	Systen	Repa			
	nstru Hitio	terati	or	Ħ	rgy	puo	Capital
	V Con	Ħ	Maj	Majc	Energ	3or	į

				New	Addit	Alter	Majo	Majo	Energ	Bond	Capit		
Year 1	Priority	BCS#	Item Description										
1	1	39	Provide an RPZ type backflow prevention device on				X				X	\$50,000	
			the main water service to prevent back siphonage.										
1	1	102	Replace the missing light fixture in the office area.				X				X	\$500	
1	1	105	Update the older Simplex fire alarm system with a new				X			X		\$100,000	
			ADA compliant fire/smoke detection system.										
1	1	106	Replace battery CO detectors with hardwired CO				X			X		\$20,000	
			detectors tied into the fire alarm panel.										
1	1	116	Expand/reconstruct office toilet room for ADA.			X					X	\$64,000	
			Requires modification of adjacent spaces in order to										
			accomplish. Replace all existing door knobs with										
			levers.										
¥7	D : :	D.C.C. II	Priority 1 Total	1	1	ı			1		1	\$234,500	
Year 2	Priority 2	42 42	Item Description Provide a supplemental tank to provide for adequate				X			X	Н	Cost \$150,000	
2	2	42	fuel oil supply during extreme cold periods.				Λ			Λ		\$130,000	
			Priority 2 Total									\$150,000	
Year 3	Priority	BCS#	Item Description									Cost	
3	3	40	Connect to the municipal sewer. This system also			X				X		\$150,000	
			handles the ECP & Teacher's Center.									,	
3	3	41	Provide a natural gas service to this building for dual				X			X		\$200,000	
			fuel firing.										
3	3	55	Repave all parking areas and replace 100 ft. of					X		Х		\$900,000	
			stockade fence.										
3	3	65	Wooden loft appears to be deflecting. Add post mid-					X			X	\$1,500	
			span & resecure wooden railing.										
3	3	65	At ground floor north side install sheet metal strip to					X			X	\$5,000	
			help slow rusting of panel bottoms at grade.										
3	3	69	Replace three exterior steel doors.					X			X	\$12,000	
3	3	87	Replace original boiler.				X			X		\$200,000	
3	3	96	Replace water heater.				X		X			\$50,000	
3	3	102	Upgrade all lighting to LED, including occupancy				X		X			\$75,000	
			sensors.										
			Priority 3 Total									\$1,593,500	
Year 4		BCS#	Item Description									Cost	
4	4	87.1	Replace short doors at D.O.T. office.					X			X	\$5,000	
4	4	92	Upgrade all controls to DDC for better control and				X		X			\$100,000	
			monitoring.		<u> </u>						Щ	A	
4	4	101	Replace original electrical panels.				X			X		\$80,000	
¥7	Dani e :::4	DCC 1	Priority 4 Total	ı	1					1		\$185,000	
Year 5	Priority 5	BC9#	Item Description								Н	Cost	
J	J		Duiquity 5 Total	<u> </u>						<u> </u>		\$0	

Priority 5 Total

\$0

Facility Total

\$2,163,000